

# Installation and Troubleshooting Guide

All rights reserved. Reproduction or use of content, in any manner, without express written permission by CDI Electronics, Inc., is prohibited



CDI P/N: 173-3668

This stator replaces P/N's: 582574, 582847, 583050, 583274 and 583668.

**WARNING!** This product is designed to be installed by a professional marine mechanic. CDI Electronics cannot be held liable for injury or damage resulting from improper installation, abuse, neglect or misuse of this product.

SERVICE NOTE: Discoloration of all the battery windings is an indication of a problem in the rectifier/regulator. Discoloration of only one post of the battery windings indicates a problem in the stator.

#### INSTALLATION

- 1. Remove the negative battery cable.
- 2. Remove the flywheel.
- 3. Disconnect the original stator wires.
- 4. Remove the original stator, saving the original bolts.
- 5. Install the new stator using the original bolts with a good thread-locker applied (CDI 989-3977 is recommended) to the bolts and tightened to the factory torque specifications.
- 6. Connect the new stator to the power pack.
- 7. Connect the new stator to the regulator/rectifier (ignore any stripes on the rectifier as the new stator does not require the Yellow wires to be connected to a particular rectifier wire).
- 8. Replace the flywheel according to the service manual.
- 9. Clean all battery cable connections, both on the battery and the engine.
- 10. Replace the battery cable.

## **TROUBLESHOOTING**

**NOTICE:** Any sign of leakage out of the high voltage coils or bubbling around the battery charge windings indicate a bad stator. Check for burned marks on each pole. If a problem is found on the battery windings, we recommend the rectifier/regulator be closely checked or replaced.

### NO FIRE ON ANY CYLINDER:

- 1. Disconnect the stop (kill) wire from the power packs and retest. If the ignition now has spark, check the stop circuit.
- 2. Check resistance between the Brown/Yellow and the Brown wires. You should read approximately 900-1100 ohms. DVA (peak voltage) should be 150v or more while connected to the power pack for each.
- 3. Inspect the flywheel outer and trigger magnets to see if they are loose or broken.
- 4. Disconnect the regulator/rectifier and retest. If the fire returns, replace the regulator/rectifier.

## NO FIRE ON ONE BANK:

- 1. Disconnect the spark plug wires from the spark plugs and install a spark gap tester (511-9766 is recommended) on all cylinders.
- 2. Swap the power packs from side to side and see if the problem moves. If it does, the power pack not sparking is likely bad.
- 3. Check the trigger leads and compare the readings for both sides. The readings should be very close.
- 4. Disconnect the stop wires and separate them. If the pack that had no spark now has spark, replace the pack that initially had spark.
- 5. Check resistance between the Brown/Yellow and the Brown wires. You should read approximately 900-1100 ohms. DVA (peak voltage) should be 150v or more while connected to the power pack for each.

## HIGH SPEED MISS-FIRE OR WEAK HOLE SHOT:

- Connect DVA meter between the Brown/Yellow and the Brown wires and do a running test on each set. AT NO TIME SHOULD
  THE VOLTAGE EXCEED 400v. If it does, the regulator circuit in the power pack is bad. The voltage should show a smooth climb
  and stabilize, gradually falling off at high RPM (above 5000). If you see a sudden drop in voltage right before the miss becomes
  apparent, the problem is likely in the stator.
- 2. Disconnect the rectifier and retest. If the problem disappears, replace the rectifier and retest.

### **OVERCHARGING THE BATTERY:**

- 1. Using a voltmeter, check the voltage on the battery and compare it to the voltage on the red wire connected to the starter solenoid to engine ground.
- 2. If the voltage is high on the engine compared to the voltage on the battery, do a voltage drop test and try to isolate the area where the problem is.
- 3. If the voltage is the same on the battery and the engine, but is over 15.5 volts at 4500 RPM, replace the battery with a known good high quality MARINE FLOODED CELL battery.