Installation Instructions

19-07-2021 (Issue 2)

WD-OPNARY-01

Parts List

Base Seal	Wedge
	
19025 1	17225 1

Optional Extra

4° Washer



WD-WP 4

Tools Required

Spanner to match device fixings.	10.5mm (5/16")
 Hole saw ø50mm (2")	Power Drill

Parts Required

 M10	Large Plain washer



Drill ø8mm holes at 90° to
Power Tower base i.e at 4° to the vertical





*Wedge not compatible with DPT

SCANSTRUT®

4° Wedge for Direct Open Array Mount - **WD-OPNARY-01**





SCANSTRUT
designed for life at sea