

How To Install Chart Light/Cigarette Lighter

For 3/16" or less panel thickness:

- Drill 7/8" diameter hole.
- If using bezel, place bezel over hole and mark location for screws before drilling holes for #6 screws.
- Insert socket through hole in bezel and then through 7/8" hole.
- Screw on case from behind panel to secure socket and bezel with #6 screws. (NOT Included)
- Push hot lead over connector & connect to power supply.
- Connect ground lead to ground tab.
- Insert lighter in socket.

For panels thicker than 3/16":

- Drill 1-1/8" diameter hole.
- Place bezel over hole and mark location for screws before drilling holes for #6 screws on 1-5/8" center.
- Follow steps(c) through (g) above.

