










Parts List			Tools Required	
M6x16mm x4	Cable Grommet x2	M8 Nylon Insulator x8		Hole Saw ø50-52mm (2")
				Power drill
60617	101819	64000		ø8.5mm (21/64") Drill Bit
Blanking Plug x1	Foam Seal x1		Parts Required	
				M8 x 25mm+ x4
101816	19020			

